## **Facility Inspection Report Blount County Correctional Facility**

Date: December 20, 2018 Members present: Sharon Hannum, James Ferguson

Time: 4:00 p.m. Members absent: Keith Brock

Others present: Officer Rick Bradley

Population: total: 612 Male: 494 Female: 118 Male: 80.72% Female: 19.28%

Public Lobby: Excellent

Public Hallways: Clean\_

Note: \*The roof and roof drains still need to be evaluated.

**Intake:** The common area is in good condition, except the floors are dirty and need to be swept and mopped. Primary bathroom needs general housekeeping. Interview room is empty and clean. Showers: Shower curtains are clean both shower stalls are clean. The deteriorated floor has been repaired. Cell #1 - Cell is occupied by 1 male dressed for placement in general population, cell is clean and no issues noted. Cell #2 – This cell is occupied by 10 undressed males and has no noticeable issues. Cell #3 – Is occupied by 7 females, who have just finished eating. Styrofoam dinnerware is stacked for removal and is otherwise clean. Cell #4 - This cell is occupied by 11 dressed males. Other than tissue on air vent in ceiling, the cell is in good condition. Cell #5 is the Garage/SALY Port area and is empty and clean. No cars are being washed at this time. Cell #6 – (Drunk Tank) This cell has 12 undressed males. The floor and commode need to be cleaned, trash is everywhere, paper stuck on ceiling air vents. Fingerprint Area - Is clean and orderly but has evidence of water leaks again. Cell #7- is reserved for female car wash crew and supplies, it is is a little disorganized and needs some housekeeping. Cell #8 is occupied by 1 male. Tissue paper is stuck to air vents and on the floor but is otherwise clean. Cell #9 – this cell is occupied by 1 male (Dominique R. Kellogg, Jr. who inquired into his status for being transferred to prison). This cell is clean. Cell #10 – This cell is occupied by 1 male and has tissue paper in ceiling air vent, and commode needs to be cleaned.

1. \*The total number of inmates in Intake is 43.

## Medical:

Exam #1 – Clean

Exam #2 - Clean.

**M-1** – Medical Supply Room – Floor is dirty.

M-2 – Floor needs to be cleaned. \*This is the low-pressure area and is not used for housing patients.

M-3 – Medical emergence happening at time of inspection and this cell could not be inspected.

M-4 – Occupied by 1 male and has tissue on air vents, floor needs to be mopped.

**M-5** – Occupied by 1 male and is clean, epoxy on floor is coming off and will need attention in the near future.

**M-6** – Occupied by 1 female and is clean.

M-7 – Occupied by 1 female and is clean except vinyl baseboards is broken in places.

M-8 – Occupied by 3 males and has no issues.

<sup>\*</sup>Administrative Office Area: Clean, ceiling tile show evidence of water leaks

- **M-9** Occupied by 4 males has tissue paper stuck to air vents and light covers, sink needs to be cleaned and sheets on one bed appear dirty.
- M-10 Occupied by 2 females, floor needs cleaned and repainted, light fixture covers also have tissue paper on .
- **M-11** Case Management worker's office. Clean and organized.
- M-12 Office for the Medical Nurse/Supervisor and Psych Nurse. Office is clean but still has some boxes that has not been unpacked.
- M-17 Dental Office. Floor really needs to be mopped and sanitized.
- M-18 Laboratory. Needs some general housekeeping.

**Shower** – Clean

Halls- \*Cleaning and trash removal occurs during the night shift by pod workers.

There are 13 inmates housed in medical at the time of this visit.

**Kitchen**: Clean-up is in progress.

Laundry: All Washers and dryers working! Area is clean.

C-Pod: \*West wall in C-5 has very wide cracks and is separated from the ceiling. Thermocycling continues to make this condition worsen. \*C-6 has the same type of deterioration as C-5. Water comes in at the foundation in C block and around windows during heavy rain events. This is an ongoing issue. \*Suggest a structural evaluation.

C-1 - Clean - (Female Pod)	C-2 _Clean – (Female Pod)
C-3 – <u>Sled Beds on floor, towels on rails</u>	C-4- Sled beds on floor, towels on rails,
C-5 – <u>Sled beds on floor, towels on rails</u>	C-6 Towels drying on rails
C-7 – Trash on floor, ceiling tile water stained	Multipurpose Room – Clean

<sup>\*</sup>It is raining today and water is evident in most pods.

<sup>\*</sup>In C-5 and C-6 Mold/ mildew can be found on the walls, in most cell areas and around windows. All corners, top and bottom need to be caulked. C-5, Water still seeps into cells during heavy rain events and is evident during today's inspection.

<sup>\*</sup>Pod Hallways - Clean

<sup>\*</sup>Food tray openings at each pod need to be pressure washed, cleaned and sanitized.

<sup>\*</sup>Some cells are more crowded than others, necessitating the use of sleds on the floors

<sup>\*</sup>Red zone areas in each Pod needs to be repainted when overcrowding allows.

<sup>\*</sup>CRC Classroom (off the hallway) needs sound panels on walls to reduce echoing and noise.

<sup>\*</sup>Gutters need to be cleaned, cracks in the stucco walls need to be repaired, there is evidence of water damage around some of the windows.

<sup>\*\*</sup>There are plans to install a French drain outside C5, C6 and C7.

D-Pod: Hallways – Clean	
D-1 Water damaged ceiling tile, floor is sticky	D-2- <u>Trash on floor@ 213, evidence of water leaks</u>
D-3 – Trash on floor, damaged ceiling tile	D-4 — Chip bags on floor, evidence of water leaks
D-5- Trash on floor@515	D-6 – No issues noted
D-7 (Recovery classroom) – Clean	Multipurpose Room – Clean
D-11 – Recreation Yard – Graffiti on wall successfully removed.	

Library: Clean and organized. Area is also a storage space.

Property Room – Clean and organized.

## **STATISTICS – Judicial Status**

State Department of Corrections (TDOC): 116

Federal Inmates: 110 Pretrial Felon: 137

Pretrial Misdemeanant: 71 Sentenced Felon: 35

Sentenced Misdemeanant: 66 House For Other Agency: 9

Repeat Offenders \*No data

<sup>\*</sup>D1 has what appears to be mold or mildew around windows.

<sup>\*</sup>D5 has an active water leak, observed dripping during visit.
THERE ARE PLANS BEING MADE FOR EVALUATION AND COST ESTIMATES FOR WATER INTRUSION ISSUES.